



Approved by: DNV GL • SFS/DMA • Loyds Register • ABS • Bureau Veritas • Rina

## - Portable Fire Extinguisher - INSPECTION REPORT

Vessel Name: <b>Dot One</b>	IMO no.: -
Carried out by: <b>SEJ / Søren Erland Jensen</b>	Month / Year: <b>March 2019</b>

No.	Location	Qty	Manufacturer	Type	Year	Kg/L	Inspected	Refilled	Weight controlled	Pressure tested	New
1	Deck	1	R.ringen	Powder	2014	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	Deck	1	R.ringen	Powder	2014	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Deck	1	R.ringen	Powder	218	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4	Deck	1	R.ringen	Powder	2015	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5	Bridge	1	Linde	Co2	2016	2 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6	Engine	1	Linde	Powder	2016	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7	Engine	1	Ginge	Co2 Pilot	2016	2 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8	Engine	1	Ginge	Powder	2016	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9	Engine	1	Ginge	Powder	2016	25 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10	Aptering	1	Ginge	Powder	2016	6 Kg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21			-	-	-	-	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Remarks:	
----------	--



*Søren Erland Jensen*

Date and stamp: 18.03.2019  
(Date-Month-Year)

Our ref: SEJ / Søren Erland Jensen

## - CO2 High Pressure system - INSPECTION REPORT

<b>Vessel Name:</b> <b>Dot One</b>	<b>IMO no.:</b> -
<b>Carried out by:</b> SEJ / Søren Erland Jensen	<b>Month / Year:</b> <b>March 2019</b>

**Description of System/Technical information:**

Type/Make : **GINGE** consisting of **4** cylinders  
 each of capacity **45kg** and **0** pilot cylinders, each of capacity **Wiretræk**  
 Nos. of distribution lines **1** last pressure test date of cylinders **03-2011**  
 Covering:

No.	Description of Inspection/Tests:	Carried out	Not carried out	Not Applicable	Note
	<input checked="" type="checkbox"/> Complete inspection <input type="checkbox"/> Contents check only				
1	Release system and distribution valves secured.:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2	Contents in cylinders checked by manual weighing.:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3	Contents in cylinders checked by liquid level indicator, cyl. temp. 5 °C	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4	Cylinders refilled or hydro tested according to report.:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5	All cylinder valves: <input checked="" type="checkbox"/> Visually inspected <input type="checkbox"/> Leak tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6	All cylinder frames and connections checked for tightness.:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7	Manifold- and distribution valves: <input checked="" type="checkbox"/> Inspected <input checked="" type="checkbox"/> Tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8	Main valve and distribution valves: <input checked="" type="checkbox"/> Inspected <input checked="" type="checkbox"/> Tested for proper operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9	Total flooding release system: <input checked="" type="checkbox"/> Inspected <input type="checkbox"/> Tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10	Release stations inspected. Wire	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11	Alarm: <input type="checkbox"/> Fan stop <input checked="" type="checkbox"/> Tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
12	Distribution lines and nozzles: <input checked="" type="checkbox"/> Inspected <input type="checkbox"/> Tested <input checked="" type="checkbox"/> Blown through	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
13	Smoke detection system tested.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
14	Doors, hinges, locks inspected.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
15	All instruction plates on installation inspected.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
16	Installation reassembled, sealed and ready for instant use, inspection date labels attached	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
18	Flexible hoses replaced Year : <b>2011</b>	Pilotsystem pressure test Year:			

Remarks:

Date and stamp: 18.03.2019  
(Date-Month-Year)



*Søren Erland Jensen*

Our ref: SEJ / Søren Erland Jensen

## - Fire detector system - INSPECTION REPORT

 Vessel Name: **Dot One**

IMO no.: -

 Carried out by: **SEJ / Søren Erland Jensen**

 Month / Year: **March 2019**

Installation type and make:

Zone	Pcs.	Description	Checked
1		Heat detector	<input type="checkbox"/>
Engine	4	Smoke detector	<input checked="" type="checkbox"/>
	1	Manual Call Point	<input checked="" type="checkbox"/>
	1	Fire alarm	<input checked="" type="checkbox"/>
2		Heat detector	<input type="checkbox"/>
Styrbord dæksly aptering	5	Smoke detector	<input checked="" type="checkbox"/>
	2	Manual Call Point	<input checked="" type="checkbox"/>
	2	Fire alarm	<input checked="" type="checkbox"/>
3		Heat detector	<input type="checkbox"/>
B.B. dæksly Styrhus	2	Smoke detector	<input checked="" type="checkbox"/>
	2	Manual Call Point	<input checked="" type="checkbox"/>
	2	Fire alarm	<input checked="" type="checkbox"/>
4		Heat detector	<input type="checkbox"/>
		Smoke detector	<input type="checkbox"/>
		Manual Call Point	<input type="checkbox"/>
		Fire alarm	<input type="checkbox"/>

1	Fault alarm inspected	<input checked="" type="checkbox"/>
2	Emergency Power Supply	<input type="checkbox"/>
3	All reassembled and ready for instant use	<input checked="" type="checkbox"/>

Emergency Batteries last changed:

Year: N/A

Month: N/A

Remarks:

 Date and stamp: 18.03.2019  
(Date-Month-Year)

 Our ref: SEJ / Søren Erland Jensen